Unit Road System

Project Status Report

Mar. 03 - Mar. 16

Rivercrest 2019 TDA Grant

Status: 50% Complete

Resurface 15,750 feet of roads

Both roller and paving machine have broken down for the second time. Staff has rented a roller. Fleet maintenance is working on the repairs.

Paving machine has been repaired. Roller is still down waiting on parts.

Airport

Status: 80% Complete

The roller has been rented. The paving machine has broken down for the second time.

Paving machine has been repaired. Crews are waiting for the weather to improve.

Pct #4 Motor Graders

Status: 85% Complete

The equipment is currently for sale in the auction.

The equipment sold at auction for \$360,500.00 each. Before commission where was a net gain of approximately \$100,000.00. The overall savings to the County on this project was approximately \$272,000. The next step is for the buyer to work with a trucking company to pick-up the equipment.

TxDOT Material Assistance Program

Status: 100% Complete

The County was approved to receive 1,000 cubic yards of RAP thru the TxDOT County Assistance Program. County crews hauled 153loads over a2-day period from 2different TxDOT sites to the County barn in Precent #1.

Oak Hill

Status: 100% Complete

It has been determined that working on the boat ramps at Oak Hill cannot be continued by the new Road and Bridge Department. As stated by the U.S. Army Corps of Engineers "the area is in violation since it is not designated as an approved boat ramp".

Tanksley Drive

Status: 100% Complete

It has been determined that Mr. Tanksley's driveway is private, and the County cannot continue to use County materials, equipment, and labor on his private driveway.

Store Room at PCT # 3 Barn

Status: 100% Complete

Project is complete.

Equipment Relocation and Consolidation

Status: 90% Complete

Moving equipment to be kept from Zavalla, PCT#2, PCT#1, and Huntington to the Burke barn. Equipment to be put up for auction is being moved to the PCT#1 barn.

Staff has continued to move equipment and supplies as time permits.

Road and Bridge Inventory

Status: 100% Complete

Staff has been working with Cody from the Auditor's office for 3 days as he performed an audit on the assets at all five barns. Between the last audit and the current audit there have been multiple commissioner changes.

Tire disposal at all County Barns

Status: 100% Complete

Crews have been working to clean up and dispose of old tires located at all five county barns. Currently, crews have disposed of approximately 100 tires and found approximately 50 tires that can be used on existing equipment.

Floating Pier at Cassels-Boykin Park

Status: 40% Complete

The gang plank section of the floating pier fell into lake Sam Rayburnwhen the lake level was high. The section of the pier was under water for approximately 2 years. The gang plank was removed for the lake in November. The gang plank was taken to a local fabricator. The guote has been obtained and given to Steve Smith for approval.

Met with the Parks Department per Steve Smith to discuss and answer any questions or concerns as to the repair of the gang plank.

County Pavement Management System

Status: 35% Complete

The management system uses inspection data from each road to calculate a pavement condition index (PCI) number. The PCI number range from zero (total failure) to 100 (excellent). This will allow for consistent description of the roads within Angelina County allowing for better maintenance and repair needs. Staff has begun working on collecting inspection data.

Staff is continuing to collect data in precinct 1 and 2.

Personnel Hiring Practices

Status: 100% Complete

Currently, The Road and Bridge Department has 8 open positions. Staff would like to start a discussion concerning the hiring of employees. Staff would like to begin the hiring process by first bring the potential employee thru a temporary service. This would allow staff to better determine if the position would be a good fit for both the County and the individual. After a determined amount of time the County would have the options of hiring the individual, extending the time to better evaluate the individual, or terminate the relationship.

Discussion is tabled

Auction of Surplus Equipment / Items

Status: 70% Complete

Staff has been working on determining what equipment is needed for the Unit Road System to operate. All the surplus equipment/itemsare being staged at the County Barn in Precinct # 1. Currently, there are approximately 34pieces of equipment/Items that are being considered for auction. Once all the items that are being considered for auction are located at the PCT #1 barn staff will contact the Commissioners Court to review and approve the list of equipment/items.

Cleaning Property on FM326

Status: 35% Complete

Crews have removed 95% of the trees and vegetation on site. Crews are using dirt on site to fill in the low areas.

Due to the weather crews have not been able to work on site.

Precinct 1

July Road

Status: 0% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

C.D. Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Arthur Drive

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Arrington Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Kay Drive

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Jacobs Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Johnny Ave.

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Keathley Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

A.K. Drive

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Blackburn Switch

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Hoage Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Tom Hampton

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Brooks Henry Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Chester Allen Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Modisette Loop

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Kirkland Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Cheeseland Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

McCarty Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Bodan Cemetery Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Choppin Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Thigpen Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Old Bonner Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Precinct 2

Jo Ann Ave.

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Fair Oaks Circle

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Redland Church Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Duncan Slough

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Winston 8 Ranch Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Redland Theatre Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Bates Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Frank Jones Road

Status: 0% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

May Ave.

Status: 0% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Precinct 3

Twin Oaks

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

John Kolb Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Whitehead Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Walker Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Charlie Porter Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Benton

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Precinct 4

Smith Wheeler

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Roy Street

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Burkhalter Hollow

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Jennings Road

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Saucedo

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Louie Cheatham Drive

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Camp

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Hoshall

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Brookwood

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Staff has verified length and width of road. Staff has determined the number of pothole and base failures. Staff will begin working on the cost estimate.

Bounds

Status: 2% Complete

The road is being funded by the 2020 Tax note. Funding per road was determined by the commissioner presiding over the precinct in 2020. Staff is working to verify the cost estimate.

Work Complaint Tally (March 03 – March 16)

Total Complaints – 88
Contacted by Phone – 86
Contacted in Person – 0
No Contact Information - 2
Completed – 176
Percent Complete - 200%

Work Complaint Tally Accumulative

Total Complaints – 756 (60 existing)
Contacted by Phone – 644
No Contact Information – 38 (35 existing complaints)
Contacted in Person – 82
Completed – 895
Open Work Orders –19
Percent Complete – 118%

Repair & Maintenance (March 03 - March 16)

Cleaned Ditches –0.45 miles Bladed Roads – 6.4 miles Driveway Culverts Installed – 4 Drainage Culverts Replaced – 1 Mowing – 44.4 miles Trees - 9

Repair & Maintenance Accumulative

Cleaned Ditches – 6.09 miles Bladed Roads – 196.7 miles Driveway Culverts Installed – 84 Drainage Culverts Replaced – 7 Mowing – 531.0 miles

For the Month of March 03 – March 16, we repaired 47 Base Failures on 10 Roads 1914 Potholes on 38 Roads

Color Legend:

Completed projects

Project status changes from prior month New projects added since last report